



Ponderosa Pool #2:  
Before preparation and application  
March 2003



Ponderosa Apartments Pool #2:  
Steps in very bad condition. Cracking, spalling, etc.



Ponderosa apartments Pool #2:  
Preparation via sandblasting and acid etching. Repair work performed using CeRam-Floor primer with high percentage of sand (we only had gray sand at the time)



Ponderosa Apartments Pool #2:  
Total resurface and repair of steps using CeRam-Floor primer and silica sand at a 7:1 ratio of sand to resin