

Residential Pool – Midland, Texas  
May 2005

**Project:** Residential swimming pool had 2-feet of concrete poured into deep end several years ago in the attempt to make the deep end more shallow. The added concrete had severely separated from original pool bottom. Original pool paint was starting to delaminate from plaster.



Large separation from poured concrete shown



Several hollow spots are needed to be repaired



Preparation included vacuum, high-pressure water blast, and degreasing several times



Steps were in need of repair, refurbishing



High-pressure water cleaning with tri-sodium phosphate detergent.



Refurbishing grout material to repair large crack and holes



Steps refurbished



CeRam-Kote 99P Blue applied in three passes

